



Abrasive Waterjet Edge Quality

The quality of the edge depends upon the speed of the cutting process. The differences between Edge 1 and Edge 3 reflect the variance of speed. Edge 1 requires more abrasion and longer cutting time; this higher quality of edge results in a higher cost.

Your Sharples rep can assist you to choose the best edge quality for your part.

